



GENERAL ANNOUNCEMENT # 06202003

Tak Cheong Electronics (Holdings) Co., Ltd. would like to announce that a product change that has been made to the following product/s would take effect immediately on June 30, 2003. This is an amendment on the Product & Process Change Notification # PCN-002 for Zener Die Change Category that was issued on December 12, 2002.

With this change, Tak Cheong Electronics Co., Ltd. would also like to inform you that all of the typical value, temperature coefficients, maximum surge capability, and etc. that was published in databook which normally presented in graphs will no longer be applicable for DO35 zener devices 56 Volts and below. See lists of all devices affected below.

For any question/s concerning contents of this announcement, please contact:

Name : Steven Zhao
Email : steven.zhao@takcheong.com
Phone : 86-660-337 5888

SUBJECT : Product & Process Change Notification # PCN-002 Amendment
TITLE : Die Change For DO35 Zeners 56 Volts and Below
CATEGORY : Zener Die Change
PRODUCT AFFECTED : All DO35 Axial Leaded Glass Zener Diodes Licensed by ON Semiconductor with Voltage Range 56 Volts and Below
EFFECTIVITY : June 30, 2003

Note: Please refer to Product & Process Change Notification # PCN-002.

ADDITIONAL CONTACT INFORMATION:

Contact/s at Tak Cheong Electronics:

SYNSEMI SEMICONDUCTOR



Name	Department	Email address	Direct line
Mr. Karl Williams	Managing Director	synsemi@yahoo.com kawsynsemi@sbcglobal.net	(1)-650-560-0095



Name	Department	Email address	Direct line
Miss. Xiao Chau	Sales & Marketing	swsales@takcheong.com	(86)-660-337-4499



Name	Department	Email address	Direct line
Ms. Jennifer Ng	Sales & Marketing	tcsales@takcheong.com	(852)-2334-1357 Ext 15



AFFECTED DEVICE LIST:

1N4370A	1N749ARR2 ;	1N756ARR1 !	1N960BTA2 *
1N4370ARL	1N750A	1N756ARR2 ;	1N960BRR1 !
1N4370ARL2 *	1N750ARL	1N757A	1N960BRR2 ;
1N4370ARA1 !	1N750ARL2 *	1N757ARL	1N961B
1N4370ARA2 ;	1N750ARA1 !	1N757ARL2 *	1N961BRL
1N4370ATA	1N750ARA2 ;	1N757ARA1 !	1N961BRL2 *
1N4370ATA2 *	1N750ATA	1N757ARA2 ;	1N961BRA1 !
1N4370ARR1 !	1N750ATA2 *	1N757ATA	1N961BRA2 ;
1N4370ARR2 ;	1N750ARR1 !	1N757ATA2 *	1N961BTA
1N4371A	1N750ARR2 ;	1N757ARR1 !	1N961BTA2 *
1N4371ARL	1N751A	1N757ARR2 ;	1N961BRR1 !
1N4371ARL2 *	1N751ARL	1N758A	1N961BRR2 ;
1N4371ARA1 !	1N751ARL2 *	1N758ARL	1N962B
1N4371ARA2 ;	1N751ARA1 !	1N758ARL2 *	1N962BRL
1N4371ATA	1N751ARA2 ;	1N758ARA1 !	1N962BRL2 *
1N4371ATA2 *	1N751ATA	1N758ARA2 ;	1N962BRA1 !
1N4371ARR1 !	1N751ATA2 *	1N758ATA	1N962BRA2 ;
1N4371ARR2 ;	1N751ARR1 !	1N758ATA2 *	1N962BTA
1N4372A	1N751ARR2 ;	1N758ARR1 !	1N962BTA2 *
1N4372ARL	1N752A	1N758ARR2 ;	1N962BRR1 !
1N4372ARL2 *	1N752ARL	1N759A	1N962BRR2 ;
1N4372ARA1 !	1N752ARL2 *	1N759ARL	1N963B
1N4372ARA2 ;	1N752ARA1 !	1N759ARL2 *	1N963BRL
1N4372ATA	1N752ARA2 ;	1N759ARA1 !	1N963BRL2 *
1N4372ATA2 *	1N752ATA	1N759ARA2 ;	1N963BRA1 !
1N4372ARR1 !	1N752ATA2 *	1N759ATA	1N963BRA2 ;
1N4372ARR2 ;	1N752ARR1 !	1N759ATA2 *	1N963BTA
1N746A	1N752ARR2 ;	1N759ARR1 !	1N963BTA2 *
1N746ARL	1N753A	1N759ARR2 ;	1N963BRR1 !
1N746ARL2 *	1N753ARL	1N957B	1N963BRR2 ;
1N746ARA1 !	1N753ARL2 *	1N957BRL	1N964B
1N746ARA2 ;	1N753ARA1 !	1N957BRL2 *	1N964BRL
1N746ATA	1N753ARA2 ;	1N957BRA1 !	1N964BRL2 *
1N746ATA2 *	1N753ATA	1N957BRA2 ;	1N964BRA1 !
1N746ARR1 !	1N753ATA2 *	1N957BTA	1N964BRA2 ;
1N746ARR2 ;	1N753ARR1 !	1N957BTA2 *	1N964BTA
1N747A	1N753ARR2 ;	1N957BRR1 !	1N964BTA2 *
1N747ARL	1N754A	1N957BRR2 ;	1N964BRR1 !
1N747ARL2 *	1N754ARL	1N958B	1N964BRR2 ;
1N747ARA1 !	1N754ARL2 *	1N958BRL	1N965B
1N747ARA2 ;	1N754ARA1 !	1N958BRL2 *	1N965BRL
1N747ATA	1N754ARA2 ;	1N958BRA1 !	1N965BRL2 *
1N747ATA2 *	1N754ATA	1N958BRA2 ;	1N965BRA1 !
1N747ARR1 !	1N754ATA2 *	1N958BTA	1N965BRA2 ;
1N747ARR2 ;	1N754ARR1 !	1N958BTA2 *	1N965BTA
1N748A	1N754ARR2 ;	1N958BRR1 !	1N965BTA2 *
1N748ARL	1N755A	1N958BRR2 ;	1N965BRR1 !
1N748ARL2 *	1N755ARL	1N959B	1N965BRR2 ;
1N748ARA1 !	1N755ARL2 *	1N959BRL	1N966B
1N748ARA2 ;	1N755ARA1 !	1N959BRL2 *	1N966BRL
1N748ATA	1N755ARA2 ;	1N959BRA1 !	1N966BRL2 *
1N748ATA2 *	1N755ATA	1N959BRA2 ;	1N966BRA1 !
1N748ARR1 !	1N755ATA2 *	1N959BTA	1N966BRA2 ;
1N748ARR2 ;	1N755ARR1 !	1N959BTA2 *	1N966BTA
1N749A	1N755ARR2 ;	1N959BRR1 !	1N966BTA2 *
1N749ARL	1N756A	1N959BRR2 ;	1N966BRR1 !
1N749ARL2 *	1N756ARL	1N960B	1N966BRR2 ;
1N749ARA1 !	1N756ARL2 *	1N960BRL	1N967B
1N749ARA2 ;	1N756ARA1 !	1N960BRL2 *	1N967BRL
1N749ATA	1N756ARA2 ;	1N960BRA1 !	1N967BRL2 *
1N749ATA2 *	1N756ATA	1N960BRA2 ;	1N967BRA1 !
1N749ARR1 !	1N756ATA2 *	1N960BTA	1N967BRA2 ;

1N967BTA	1N974BRR1!	1N5987B	1N5994BRL2*
1N967BTA2*	1N974BRR2;	1N5987BRL	1N5994BRA1!
1N967BRR1!	1N975B	1N5987BRL2*	1N5994BRA2;
1N967BRR2;	1N975BRL	1N5987BRA1!	1N5994BTA
1N968B	1N975BRL2*	1N5987BRA2;	1N5994BTA2*
1N968BRL	1N975BRA1!	1N5987BTA	1N5994BRR1!
1N968BRL2*	1N975BRA2;	1N5987BTA2*	1N5994BRR2;
1N968BRA1!	1N975BTA	1N5987BRR1!	1N5995B
1N968BRA2;	1N975BTA2*	1N5987BRR2;	1N5995BRL
1N968BTA	1N975BRR1!	1N5988B	1N5995BRL2*
1N968BTA2*	1N975BRR2;	1N5988BRL	1N5995BRA1!
1N968BRR1!	1N976B	1N5988BRL2*	1N5995BRA2;
1N968BRR2;	1N976BRL	1N5988BRA1!	1N5995BTA
1N969B	1N976BRL2*	1N5988BRA2;	1N5995BTA2*
1N969BRL	1N976BRA1!	1N5988BTA	1N5995BRR1!
1N969BRL2*	1N976BRA2;	1N5988BTA2*	1N5995BRR2;
1N969BRA1!	1N976BTA	1N5988BRR1!	1N5996B
1N969BRA2;	1N976BTA2*	1N5988BRR2;	1N5996BRL
1N969BTA	1N976BRR1!	1N5989B	1N5996BRL2*
1N969BTA2*	1N976BRR2;	1N5989BRL	1N5996BRA1!
1N969BRR1!	1N977B	1N5989BRL2*	1N5996BRA2;
1N969BRR2;	1N977BRL	1N5989BRA1!	1N5996BTA
1N970B	1N977BRL2*	1N5989BRA2;	1N5996BTA2*
1N970BRL	1N977BRA1!	1N5989BTA	1N5996BRR1!
1N970BRL2*	1N977BRA2;	1N5989BTA2*	1N5996BRR2;
1N970BRA1!	1N977BTA	1N5989BRR1!	1N5997B
1N970BRA2;	1N977BTA2*	1N5989BRR2;	1N5997BRL
1N970BTA	1N977BRR1!	1N5990B	1N5997BRL2*
1N970BTA2*	1N977BRR2;	1N5990BRL	1N5997BRA1!
1N970BRR1!	1N978B	1N5990BRL2*	1N5997BRA2;
1N970BRR2;	1N978BRL	1N5990BRA1!	1N5997BTA
1N971B	1N978BRL2*	1N5990BRA2;	1N5997BTA2*
1N971BRL	1N978BRA1!	1N5990BTA	1N5997BRR1!
1N971BRL2*	1N978BRA2;	1N5990BTA2*	1N5997BRR2;
1N971BRA1!	1N978BTA	1N5990BRR1!	1N5998B
1N971BRA2;	1N978BTA2*	1N5990BRR2;	1N5998BRL
1N971BTA	1N978BRR1!	1N5991B	1N5998BRL2*
1N971BTA2*	1N978BRR2;	1N5991BRL	1N5998BRA1!
1N971BRR1!	1N979B	1N5991BRL2*	1N5998BRA2;
1N971BRR2;	1N979BRL	1N5991BRA1!	1N5998BTA
1N972B	1N979BRL2*	1N5991BRA2;	1N5998BTA2*
1N972BRL	1N979BRA1!	1N5991BTA	1N5998BRR1!
1N972BRL2*	1N979BRA2;	1N5991BTA2*	1N5998BRR2;
1N972BRA1!	1N979BTA	1N5991BRR1!	1N5999B
1N972BRA2;	1N979BTA2*	1N5991BRR2;	1N5999BRL
1N972BTA	1N979BRR1!	1N5992B	1N5999BRL2*
1N972BTA2*	1N979BRR2;	1N5992BRL	1N5999BRA1!
1N972BRR1!	1N5985B	1N5992BRL2*	1N5999BRA2;
1N972BRR2;	1N5985BRL	1N5992BRA1!	1N5999BTA
1N973B	1N5985BRL2*	1N5992BRA2;	1N5999BTA2*
1N973BRL	1N5985BRA1!	1N5992BTA	1N5999BRR1!
1N973BRL2*	1N5985BRA2;	1N5992BTA2*	1N5999BRR2;
1N973BRA1!	1N5985BTA	1N5992BRR1!	1N6000B
1N973BRA2;	1N5985BTA2*	1N5992BRR2;	1N6000BRL
1N973BTA	1N5985BRR1!	1N5993B	1N6000BRL2*
1N973BTA2*	1N5985BRR2;	1N5993BRL	1N6000BRA1!
1N973BRR1!	1N5986B	1N5993BRL2*	1N6000BRA2;
1N973BRR2;	1N5986BRL	1N5993BRA1!	1N6000BTA
1N974B	1N5986BRL2*	1N5993BRA2;	1N6000BTA2*
1N974BRL	1N5986BRA1!	1N5993BTA	1N6000BRR1!
1N974BRL2*	1N5986BRA2;	1N5993BTA2*	1N6000BRR2;
1N974BRA1!	1N5986BTA	1N5993BRR1!	1N6001B
1N974BRA2;	1N5986BTA2*	1N5993BRR2;	1N6001BRL
1N974BTA	1N5986BRR1!	1N5994B	1N6001BRL2*
1N974BTA2*	1N5986BRR2;	1N5994BRL	1N6001BRA1!

1N6001BRA2;	1N6008BTA2*	1N6015BRR2;	1N5225BRL
1N6001BTA	1N6008BRR1!	1N6016B	1N5225BRL2*
1N6001BTA2*	1N6008BRR2;	1N6016BRL	1N5225BRA1!
1N6001BRR1!	1N6009B	1N6016BRL2*	1N5225BRA2;
1N6001BRR2;	1N6009BRL	1N6016BRA1!	1N5225BTA
1N6002B	1N6009BRL2*	1N6016BRA2;	1N5225BTA2*
1N6002BRL	1N6009BRA1!	1N6016BTA	1N5225BRR1!
1N6002BRL2*	1N6009BRA2;	1N6016BTA2*	1N5225BRR2;
1N6002BRA1!	1N6009BTA	1N6016BRR1!	1N5226B
1N6002RA2;	1N6009BTA2*	1N6016BRR2;	1N5226BRL
1N6002BTA	1N6009BRR1!	1N6017B	1N5226BRL2*
1N6002BTA2*	1N6009BRR2;	1N6017BRL	1N5226BRA1!
1N6002BRR1!	1N6010B	1N6017BRL2*	1N5226BRA2;
1N6002BRR2;	1N6010BRL	1N6017BRA1!	1N5226BTA
1N6003B	1N6010BRL2*	1N6017BRA2;	1N5226BTA2*
1N6003BRL	1N6010BRA1!	1N6017BTA	1N5226BRR1!
1N6003BRL2*	1N6010BRA2;	1N6017BTA2*	1N5226BRR2;
1N6003BRA1!	1N6010BTA	1N6017BRR1!	1N5227B
1N6003BRA2;	1N6010BTA2*	1N6017BRR2;	1N5227BRL
1N6003BTA	1N6010BRR1!	1N6018B	1N5227BRL2*
1N6003BTA2*	1N6010BRR2;	1N6018BRL	1N5227BRA1!
1N6003BRR1!	1N6011B	1N6018BRL2*	1N5227BRA2;
1N6003BRR2;	1N6011BRL	1N6018BRA1!	1N5227BTA
1N6004B	1N6011BRL2*	1N6018BRA2;	1N5227BTA2*
1N6004BRL	1N6011BRA1!	1N6018BTA	1N5227BRR1!
1N6004BRL2*	1N6011BRA2;	1N6018BTA2*	1N5227BRR2;
1N6004BRA1!	1N6011BTA	1N6018BRR1!	1N5228B
1N6004BRA2;	1N6011BTA2*	1N6018BRR2;	1N5228BRL
1N6004BTA	1N6011BRR1!	1N5221B	1N5228BRL2*
1N6004BTA2*	1N6011BRR2;	1N5221BRL	1N5228BRA1!
1N6004BRR1!	1N6012B	1N5221BRL2*	1N5228BRA2;
1N6004BRR2;	1N6012BRL	1N5221BRA1!	1N5228BTA
1N6005B	1N6012BRL2*	1N5221BRA2;	1N5228BTA2*
1N6005BRL	1N6012BRA1!	1N5221BTA	1N5228BRR1!
1N6005BRL2*	1N6012BRA2;	1N5221BTA2*	1N5228BRR2;
1N6005BRA1!	1N6012BTA	1N5221BRR1!	1N5229B
1N6005BRA2;	1N6012BTA2*	1N5221BRR2;	1N5229BRL
1N6005BTA	1N6012BRR1!	1N5222B	1N5229BRL2*
1N6005BTA2*	1N6012BRR2;	1N5222BRL	1N5229BRA1!
1N6005BRR1!	1N6013B	1N5222BRL2*	1N5229BRA2;
1N6005BRR2;	1N6013BRL	1N5222BRA1!	1N5229BTA
1N6006B	1N6013BRL2*	1N5222BRA2;	1N5229BTA2*
1N6006BRL	1N6013BRA1!	1N5222BTA	1N5229BRR1!
1N6006BRL2*	1N6013BRA2;	1N5222BTA2*	1N5229BRR2;
1N6006BRA1!	1N6013BTA	1N5222BRR1!	1N5230B
1N6006BRA2;	1N6013BTA2*	1N5222BRR2;	1N5230BRL
1N6006BTA	1N6013BRR1!	1N5223B	1N5230BRL2*
1N6006BTA2*	1N6013BRR2;	1N5223BRL	1N5230BRA1!
1N6006BRR1!	1N6014B	1N5223BRL2*	1N5230BRA2;
1N6006BRR2;	1N6014BRL	1N5223BRA1!	1N5230BTA
1N6007B	1N6014BRL2*	1N5223BRA2;	1N5230BTA2*
1N6007BRL	1N6014BRA1!	1N5223BTA	1N5230BRR1!
1N6007BRL2*	1N6014BRA2;	1N5223BTA2*	1N5230BRR2;
1N6007BRA1!	1N6014BTA	1N5223BRR1!	1N5231B
1N6007BRA2;	1N6014BTA2*	1N5223BRR2;	1N5231BRL
1N6007BTA	1N6014BRR1!	1N5224B	1N5231BRL2*
1N6007BTA2*	1N6014BRR2;	1N5224BRL	1N5231BRA1!
1N6007BRR1!	1N6015B	1N5224BRL2*	1N5231BRA2;
1N6007BRR2;	1N6015BRL	1N5224BRA1!	1N5231BTA
1N6008B	1N6015BRL2*	1N5224BRA2;	1N5231BTA2*
1N6008BRL	1N6015BRA1!	1N5224BTA	1N5231BRR1!
1N6008BRL2*	1N6015BRA2;	1N5224BTA2*	1N5231BRR2;
1N6008BRA1!	1N6015BTA	1N5224BRR1!	1N5232B
1N6008BRA2;	1N6015BTA2*	1N5224BRR2;	1N5232BRL
1N6008BTA	1N6015BRR1!	1N5225B	1N5232BRL2*

1N5232BRA1!	1N5239BTA	1N5246BRR1!	1N5254B
1N5232BRA2;	1N5239BTA2*	1N5246BRR2;	1N5254BRL
1N5232BTA	1N5239BRR1!	1N5247B	1N5254BRL2*
1N5232BTA2*	1N5239BRR2;	1N5247BRL	1N5254BRA1!
1N5232BRR1!	1N5240B	1N5247BRL2*	1N5254BRA2;
1N5232BRR2;	1N5240BRL	1N5247BRA1!	1N5254BTA
1N5233B	1N5240BRL2*	1N5247BRA2;	1N5254BTA2*
1N5233BRL	1N5240BRA1!	1N5247BTA	1N5254BRR1!
1N5233BRL2*	1N5240BRA2;	1N5247BTA2*	1N5254BRR2;
1N5233BRA1!	1N5240BTA	1N5247BRR1!	1N5255B
1N5233BRA2;	1N5240BTA2*	1N5247BRR2;	1N5255BRL
1N5233BTA	1N5240BRR1!	1N5248B	1N5255BRL2*
1N5233BTA2*	1N5240BRR2;	1N5248BRL	1N5255BRA1!
1N5233BRR1!	1N5241B	1N5248BRL2*	1N5255BRA2;
1N5233BRR2;	1N5241BRL	1N5248BRA1!	1N5255BTA
1N5234B	1N5241BRL2*	1N5248BRA2;	1N5255BTA2*
1N5234BRL	1N5241BRA1!	1N5248BTA	1N5255BRR1!
1N5234BRL2*	1N5241BRA2;	1N5248BTA2*	1N5255BRR2;
1N5234BRA1!	1N5241BTA	1N5248BRR1!	1N5256B
1N5234BRA2;	1N5241BTA2*	1N5248BRR2;	1N5256BRL
1N5234BTA	1N5241BRR1!	1N5249B	1N5256BRL2*
1N5234BTA2*	1N5241BRR2;	1N5249BRL	1N5256BRA1!
1N5234BRR1!	1N5242B	1N5249BRL2*	1N5256BRA2;
1N5234BRR2;	1N5242BRL	1N5249BRA1!	1N5256BTA
1N5235B	1N5242BRL2*	1N5249BRA2;	1N5256BTA2*
1N5235BRL	1N5242BRA1!	1N5249BTA	1N5256BRR1!
1N5235BRL2*	1N5242BRA2;	1N5249BTA2*	1N5256BRR2;
1N5235BRA1!	1N5242BTA	1N5249BRR1!	1N5257B
1N5235BRA2;	1N5242BTA2*	1N5249BRR2;	1N5257BRL
1N5235BTA	1N5242BRR1!	1N5250B	1N5257BRL2*
1N5235BTA2*	1N5242BRR2;	1N5250BRL	1N5257BRA1!
1N5235BRR1!	1N5243B	1N5250BRL2*	1N5257BRA2;
1N5235BRR2;	1N5243BRL	1N5250BRA1!	1N5257BTA
1N5236B	1N5243BRL2*	1N5250BRA2;	1N5257BTA2*
1N5236BRL	1N5243BRA1!	1N5250BTA	1N5257BRR1!
1N5236BRL2*	1N5243BRA2;	1N5250BTA2*	1N5257BRR2;
1N5236BRA1!	1N5243BTA	1N5250BRR1!	1N5258B
1N5236BRA2;	1N5243BTA2*	1N5250BRR2;	1N5258BRL
1N5236BTA	1N5243BRR1!	1N5251B	1N5258BRL2*
1N5236BTA2*	1N5243BRR2;	1N5251BRL	1N5258BRA1!
1N5236BRR1!	1N5244B	1N5251BRL2*	1N5258BRA2;
1N5236BRR2;	1N5244BRL	1N5251BRA1!	1N5258BTA
1N5237B	1N5244BRL2*	1N5251BRA2;	1N5258BTA2*
1N5237BRL	1N5244BRA1!	1N5251BTA	1N5258BRR1!
1N5237BRL2*	1N5244BRA2;	1N5251BTA2*	1N5258BRR2;
1N5237BRA1!	1N5244BTA	1N5251BRR1!	1N5259B
1N5237BRA2;	1N5244BTA2*	1N5251BRR2;	1N5259BRL
1N5237BTA	1N5244BRR1!	1N5252B	1N5259BRL2*
1N5237BTA2*	1N5244BRR2;	1N5252BRL	1N5259BRA1!
1N5237BRR1!	1N5245B	1N5252BRL2*	1N5259BRA2;
1N5237BRR2;	1N5245BRL	1N5252BRA1!	1N5259BTA
1N5238B	1N5245BRL2*	1N5252BRA2;	1N5259BTA2*
1N5238BRL	1N5245BRA1!	1N5252BTA	1N5259BRR1!
1N5238BRL2*	1N5245BRA2;	1N5252BTA2*	1N5259BRR2;
1N5238BRA1!	1N5245BTA	1N5252BRR1!	1N5260B
1N5238BRA2;	1N5245BTA2*	1N5252BRR2;	1N5260BRL
1N5238BTA	1N5245BRR1!	1N5253B	1N5260BRL2*
1N5238BTA2*	1N5245BRR2;	1N5253BRL	1N5260BRA1!
1N5238BRR1!	1N5246B	1N5253BRL2*	1N5260BRA2;
1N5238BRR2;	1N5246BRL	1N5253BRA1!	1N5260BTA
1N5239B	1N5246BRL2*	1N5253BRA2;	1N5260BTA2*
1N5239BRL	1N5246BRA1!	1N5253BTA	1N5260BRR1!
1N5239BRL2*	1N5246BRA2;	1N5253BTA2*	1N5260BRR2;
1N5239BRA1!	1N5246BTA	1N5253BRR1!	1N5261B
1N5239BRA2;	1N5246BTA2*	1N5253BRR2;	1N5261BRL



- | | | | |
|---------------|---------------|---------------|--------------|
| 1N5261BRL2* | BZX55C3V6RA2; | BZX55C6V8RR2; | BZX55C15RL |
| 1N5261BRA1! | BZX55C3V6TA | BZX55C7V5 | BZX55C15RL2* |
| 1N5261BRA2; | BZX55C3V6TA2* | BZX55C7V5RL | BZX55C15RA1! |
| 1N5261BTA | BZX55C3V9 | BZX55C7V5RL2* | BZX55C15RA2; |
| 1N5261BTA2* | BZX55C3V9RL | BZX55C7V5RA1! | BZX55C15TA |
| 1N5261BRR1! | BZX55C3V9RL2* | BZX55C7V5RA2; | BZX55C15TA2* |
| 1N5261BRR2; | BZX55C3V9RA1! | BZX55C7V5TA | BZX55C15RR1! |
| 1N5262B | BZX55C3V9RA2; | BZX55C7V5TA2* | BZX55C15RR2; |
| 1N5262BRL | BZX55C3V9TA | BZX55C7V5RR1! | BZX55C16 |
| 1N5262BRL2* | BZX55C3V9TA2* | BZX55C7V5RR2; | BZX55C16RL |
| 1N5262BRA1! | BZX55C3V9RR1! | BZX55C8V2 | BZX55C16RL2* |
| 1N5262BRA2; | BZX55C3V9RR2; | BZX55C8V2RL | BZX55C16RA1! |
| 1N5262BTA | BZX55C4V3 | BZX55C8V2RL2* | BZX55C16RA2; |
| 1N5262BTA2* | BZX55C4V3RL | BZX55C8V2RA1! | BZX55C16TA |
| 1N5262BRR1! | BZX55C4V3RL2* | BZX55C8V2RA2; | BZX55C16TA2* |
| 1N5262BRR2; | BZX55C4V3RA1! | BZX55C8V2TA | BZX55C16RR1! |
| 1N5263B | BZX55C4V3RA2; | BZX55C8V2TA2* | BZX55C16RR2; |
| 1N5263BRL | BZX55C4V3TA | BZX55C8V2RR1! | BZX55C18 |
| 1N5263BRL2* | BZX55C4V3TA2* | BZX55C8V2RR2; | BZX55C18RL |
| 1N5263BRA1! | BZX55C4V3RR1! | BZX55C9V1 | BZX55C18RL2* |
| 1N5263BRA2; | BZX55C4V3RR2; | BZX55C9V1RL | BZX55C18RA1! |
| 1N5263BTA | BZX55C4V7 | BZX55C9V1RL2* | BZX55C18RA2; |
| 1N5263BTA2* | BZX55C4V7RL | BZX55C9V1RA1! | BZX55C18TA |
| 1N5263BRR1! | BZX55C4V7RL2* | BZX55C9V1RA2; | BZX55C18TA2* |
| 1N5263BRR2; | BZX55C4V7RA1! | BZX55C9V1TA | BZX55C18RR1! |
| BZX55C2V4 | BZX55C4V7RA2; | BZX55C9V1TA2* | BZX55C18RR2; |
| BZX55C2V4RL | BZX55C4V7TA | BZX55C9V1RR1! | BZX55C20 |
| BZX55C2V4RL2* | BZX55C4V7TA2* | BZX55C9V1RR2; | BZX55C20RL |
| BZX55C2V4RA1! | BZX55C4V7RR1! | BZX55C10 | BZX55C20RL2* |
| BZX55C2V4RA2; | BZX55C4V7RR2; | BZX55C10RL | BZX55C20RA1! |
| BZX55C2V4TA | BZX55C5V1 | BZX55C10RL2* | BZX55C20RA2; |
| BZX55C2V4TA2* | BZX55C5V1RL | BZX55C10RA1! | BZX55C20TA |
| BZX55C2V4RR1! | BZX55C5V1RL2* | BZX55C10RA2; | BZX55C20TA2* |
| BZX55C2V4RR2; | BZX55C5V1RA1! | BZX55C10TA | BZX55C20RR1! |
| BZX55C2V7 | BZX55C5V1RA2; | BZX55C10TA2* | BZX55C20RR2; |
| BZX55C2V7RL | BZX55C5V1TA | BZX55C10RR1! | BZX55C22 |
| BZX55C2V7RL2* | BZX55C5V1TA2* | BZX55C10RR2; | BZX55C22RL |
| BZX55C2V7RA1! | BZX55C5V1RR1! | BZX55C11 | BZX55C22RL2* |
| BZX55C2V7RA2; | BZX55C5V1RR2; | BZX55C11RL | BZX55C22RA1! |
| BZX55C2V7TA | BZX55C5V6 | BZX55C11RL2* | BZX55C22RA2; |
| BZX55C2V7TA2* | BZX55C5V6RL | BZX55C11RA1! | BZX55C22TA |
| BZX55C2V7RR1! | BZX55C5V6RL2* | BZX55C11RA2; | BZX55C22TA2* |
| BZX55C2V7RR2; | BZX55C5V6RA1! | BZX55C11TA | BZX55C22RR1! |
| BZX55C3V0 | BZX55C5V6RA2; | BZX55C11TA2* | BZX55C22RR2; |
| BZX55C3V0RL | BZX55C5V6TA | BZX55C11RR1! | BZX55C24 |
| BZX55C3V0RL2* | BZX55C5V6TA2* | BZX55C11RR2; | BZX55C24RL |
| BZX55C3V0RA1! | BZX55C5V6RR1! | BZX55C12 | BZX55C24RL2* |
| BZX55C3V0RA2; | BZX55C5V6RR2; | BZX55C12RL | BZX55C24RA1! |
| BZX55C3V0TA | BZX55C6V2 | BZX55C12RL2* | BZX55C24RA2; |
| BZX55C3V0TA2* | BZX55C6V2RL | BZX55C12RA1! | BZX55C24TA |
| BZX55C3V0RR1! | BZX55C6V2RL2* | BZX55C12RA2; | BZX55C24TA2* |
| BZX55C3V0RR2; | BZX55C6V2RA1! | BZX55C12TA | BZX55C24RR1! |
| BZX55C3V3 | BZX55C6V2RA2; | BZX55C12TA2* | BZX55C24RR2; |
| BZX55C3V3RL | BZX55C6V2TA | BZX55C12RR1! | BZX55C27 |
| BZX55C3V3RL2* | BZX55C6V2TA2* | BZX55C12RR2; | BZX55C27RL |
| BZX55C3V3RA1! | BZX55C6V2RR1! | BZX55C13 | BZX55C27RL2* |
| BZX55C3V3RA2; | BZX55C6V2RR2; | BZX55C13RL | BZX55C27RA1! |
| BZX55C3V3TA | BZX55C6V8 | BZX55C13RL2* | BZX55C27RA2; |
| BZX55C3V3TA2* | BZX55C6V8RL | BZX55C13RA1! | BZX55C27TA |
| BZX55C3V3RR1! | BZX55C6V8RL2* | BZX55C13RA2; | BZX55C27TA2* |
| BZX55C3V3RR2; | BZX55C6V8RA1! | BZX55C13TA | BZX55C27RR1! |
| BZX55C3V6 | BZX55C6V8RA2; | BZX55C13TA2* | BZX55C27RR2; |
| BZX55C3V6RL | BZX55C6V8TA | BZX55C13RR1! | BZX55C30 |
| BZX55C3V6RL2* | BZX55C6V8TA2* | BZX55C13RR2; | BZX55C30RL |
| BZX55C3V6RA1! | BZX55C6V8RR1! | BZX55C15 | BZX55C30RL2* |

BZX55C30RA1!	BZX55C56TA	BZX79C4V7	BZX79C9V1RL2*
BZX55C30RA2;	BZX55C56TA2*	BZX79C4V7RL	BZX79C9V1RA1!
BZX55C30TA	BZX55C56RR1!	BZX79C4V7RL2*	BZX79C9V1RA2;
BZX55C30TA2*	BZX55C56RR2;	BZX79C4V7RA1!	BZX79C9V1TA
BZX55C30RR1!	BZX79C2V4	BZX79C4V7RA2;	BZX79C9V1TA2*
BZX55C30RR2;	BZX79C2V4RL	BZX79C4V7TA	BZX79C9V1RR1!
BZX55C33	BZX79C2V4RL2*	BZX79C4V7TA2*	BZX79C9V1RR2;
BZX55C33RL	BZX79C2V4RA1!	BZX79C4V7RR1!	BZX79C10
BZX55C33RL2*	BZX79C2V4RA2;	BZX79C4V7RR2;	BZX79C10RL
BZX55C33RA1!	BZX79C2V4TA	BZX79C5V1	BZX79C10RL2*
BZX55C33RA2;	BZX79C2V4TA2*	BZX79C5V1RL	BZX79C10RA1!
BZX55C33TA	BZX79C2V4RR1!	BZX79C5V1RL2*	BZX79C10RA2;
BZX55C33TA2*	BZX79C2V4RR2;	BZX79C5V1RA1!	BZX79C10TA
BZX55C33RR1!	BZX79C2V7	BZX79C5V1RA2;	BZX79C10TA2*
BZX55C33RR2;	BZX79C2V7RL	BZX79C5V1TA	BZX79C10RR1!
BZX55C36	BZX79C2V7RL2*	BZX79C5V1TA2*	BZX79C10RR2;
BZX55C36RL	BZX79C2V7RA1!	BZX79C5V1RR1!	BZX79C11
BZX55C36RL2*	BZX79C2V7RA2;	BZX79C5V1RR2;	BZX79C11RL
BZX55C36RA1!	BZX79C2V7TA	BZX79C5V6	BZX79C11RL2*
BZX55C36RA2;	BZX79C2V7TA2*	BZX79C5V6RL	BZX79C11RA1!
BZX55C36TA	BZX79C2V7RR1!	BZX79C5V6RL2*	BZX79C11RA2;
BZX55C36TA2*	BZX79C2V7RR2;	BZX79C5V6RA1!	BZX79C11TA
BZX55C36RR1!	BZX79C3V0	BZX79C5V6RA2;	BZX79C11TA2*
BZX55C36RR2;	BZX79C3V0RL	BZX79C5V6TA	BZX79C11RR1!
BZX55C39	BZX79C3V0RL2*	BZX79C5V6TA2*	BZX79C11RR2;
BZX55C39RL	BZX79C3V0RA1!	BZX79C5V6RR1!	BZX79C12
BZX55C39RL2*	BZX79C3V0RA2;	BZX79C5V6RR2;	BZX79C12RL
BZX55C39RA1!	BZX79C3V0TA	BZX79C6V2	BZX79C12RL2*
BZX55C39RA2;	BZX79C3V0TA2*	BZX79C6V2RL	BZX79C12RA1!
BZX55C39TA	BZX79C3V0RR1!	BZX79C6V2RL2*	BZX79C12RA2;
BZX55C39TA2*	BZX79C3V0RR2;	BZX79C6V2RA1!	BZX79C12TA
BZX55C39RR1!	BZX79C3V3	BZX79C6V2RA2;	BZX79C12TA2*
BZX55C39RR2;	BZX79C3V3RL	BZX79C6V2TA	BZX79C12RR1!
BZX55C43	BZX79C3V3RL2*	BZX79C6V2TA2*	BZX79C12RR2;
BZX55C43RL	BZX79C3V3RA1!	BZX79C6V2RR1!	BZX79C13
BZX55C43RL2*	BZX79C3V3RA2;	BZX79C6V2RR2;	BZX79C13RL
BZX55C43RA1!	BZX79C3V3TA	BZX79C6V8	BZX79C13RL2*
BZX55C43RA2;	BZX79C3V3TA2*	BZX79C6V8RL	BZX79C13RA1!
BZX55C43TA	BZX79C3V3RR1!	BZX79C6V8RL2*	BZX79C13RA2;
BZX55C43TA2*	BZX79C3V3RR2;	BZX79C6V8RA1!	BZX79C13TA
BZX55C43RR1!	BZX79C3V6	BZX79C6V8RA2;	BZX79C13TA2*
BZX55C43RR2;	BZX79C3V6RL	BZX79C6V8TA	BZX79C13RR1!
BZX55C47	BZX79C3V6RL2*	BZX79C6V8TA2*	BZX79C13RR2;
BZX55C47RL	BZX79C3V6RA1!	BZX79C6V8RR1!	BZX79C15
BZX55C47RL2*	BZX79C3V6RA2;	BZX79C6V8RR2;	BZX79C15RL
BZX55C47RA1!	BZX79C3V6TA	BZX79C7V5	BZX79C15RL2*
BZX55C47RA2;	BZX79C3V6TA2*	BZX79C7V5RL	BZX79C15RA1!
BZX55C47TA	BZX79C3V9	BZX79C7V5RL2*	BZX79C15RA2;
BZX55C47TA2*	BZX79C3V9RL	BZX79C7V5RA1!	BZX79C15TA
BZX55C47RR1!	BZX79C3V9RL2*	BZX79C7V5RA2;	BZX79C15TA2*
BZX55C47RR2;	BZX79C3V9RA1!	BZX79C7V5TA	BZX79C15RR1!
BZX55C51	BZX79C3V9RA2;	BZX79C7V5TA2*	BZX79C15RR2;
BZX55C51RL	BZX79C3V9TA	BZX79C7V5RR1!	BZX79C16
BZX55C51RL2*	BZX79C3V9TA2*	BZX79C7V5RR2;	BZX79C16RL
BZX55C51RA1!	BZX79C3V9RR1!	BZX79C8V2	BZX79C16RL2*
BZX55C51RA2;	BZX79C3V9RR2;	BZX79C8V2RL	BZX79C16RA1!
BZX55C51TA	BZX79C4V3	BZX79C8V2RL2*	BZX79C16RA2;
BZX55C51TA2*	BZX79C4V3RL	BZX79C8V2RA1!	BZX79C16TA
BZX55C51RR1!	BZX79C4V3RL2*	BZX79C8V2RA2;	BZX79C16TA2*
BZX55C51RR2;	BZX79C4V3RA1!	BZX79C8V2TA	BZX79C16RR1!
BZX55C56	BZX79C4V3RA2;	BZX79C8V2TA2*	BZX79C16RR2;
BZX55C56RL	BZX79C4V3TA	BZX79C8V2RR1!	BZX79C18
BZX55C56RL2*	BZX79C4V3TA2*	BZX79C8V2RR2;	BZX79C18RL
BZX55C56RA1!	BZX79C4V3RR1!	BZX79C9V1	BZX79C18RL2*
BZX55C56RA2;	BZX79C4V3RR2;	BZX79C9V1RL	BZX79C18RA1!



BZX79C18RA2 ;
BZX79C18TA
BZX79C18TA2*
BZX79C18RR1!
BZX79C18RR2 ;
BZX79C20
BZX79C20RL
BZX79C20RL2*
BZX79C20RA1!
BZX79C20RA2 ;
BZX79C20TA
BZX79C20TA2*
BZX79C20RR1!
BZX79C20RR2 ;
BZX79C22
BZX79C22RL
BZX79C22RL2*
BZX79C22RA1!
BZX79C22RA2 ;
BZX79C22TA
BZX79C22TA2*
BZX79C22RR1!
BZX79C22RR2 ;
BZX79C24
BZX79C24RL
BZX79C24RL2*
BZX79C24RA1!
BZX79C24RA2 ;
BZX79C24TA
BZX79C24TA2*
BZX79C24RR1!
BZX79C24RR2 ;
BZX79C27
BZX79C27RL
BZX79C27RL2*
BZX79C27RA1!
BZX79C27RA2 ;
BZX79C27TA
BZX79C27TA2*
BZX79C27RR1!
BZX79C27RR2 ;
BZX79C30
BZX79C30RL
BZX79C30RL2*
BZX79C30RA1!
BZX79C30RA2 ;
BZX79C30TA
BZX79C30TA2*
BZX79C30RR1!
BZX79C30RR2 ;
BZX79C33
BZX79C33RL
BZX79C33RL2*
BZX79C33RA1!
BZX79C33RA2 ;
BZX79C33TA
BZX79C33TA2*
BZX79C33RR1!
BZX79C33RR2 ;
BZX79C36
BZX79C36RL
BZX79C36RL2*
BZX79C36RA1!
BZX79C36RA2 ;
BZX79C36TA
BZX79C36TA2*
BZX79C36RR1!
BZX79C36RR2 ;
BZX79C39
BZX79C39RL
BZX79C39RL2*
BZX79C39RA1!
BZX79C39RA2 ;
BZX79C39TA
BZX79C39TA2*
BZX79C39RR1!
BZX79C39RR2 ;
BZX79C43
BZX79C43RL
BZX79C43RL2*
BZX79C43RA1!
BZX79C43RA2 ;
BZX79C43TA
BZX79C43TA2*
BZX79C43RR1!
BZX79C43RR2 ;
BZX79C47
BZX79C47RL
BZX79C47RL2*
BZX79C47RA1!
BZX79C47RA2 ;
BZX79C47TA
BZX79C47TA2*
BZX79C47RR1!
BZX79C47RR2 ;
BZX79C51
BZX79C51RL
BZX79C51RL2*
BZX79C51RA1!
BZX79C51RA2 ;
BZX79C51TA
BZX79C51TA2*
BZX79C51RR1!
BZX79C51RR2 ;
BZX79C56
BZX79C56RL
BZX79C56RL2*
BZX79C56RA1!
BZX79C56RA2 ;
BZX79C56TA
BZX79C56TA2*
BZX79C56RR1!
BZX79C56RR2 ;